Wayne's Auto Appraisal



10 Emerald Aenue Clarenville DLL 466 - 2580

WAYNE'S AUTO APPRAISAL 709-466-2580

This Automobile Appraisal report consists of two sections: A Vehicle Identification Section and A Vehicle Evaluation Section.

Vehicle Identification Section

The Vehicle Identification Section provides you and the appraiser with detailed information about your vehicle. This information helps the appraiser to research your vehicle accurately and provides the foundation for a precise and reliable appraisal. You should examine the information in this section for accuracy and inform the appraiser of any changes.

Vehicle Evaluation Section

The *Vehicle Evaluation Section* reports the results of the evaluation conducted by the appraiser. This section begins with the appraiser's comments about the overall appearance of your vehicle. This is followed by the detailed 320-point evaluation which includes the *component* examined, the range of points and the appraiser's *grade*. The component is the item on your vehicle that is being evaluated, such as the front driver's seat or exhaust system. Next comes the range of points available for the components being examined. Then comes the grade for your vehicle's component; the lower the number, the less your vehicle's component resembles a new-vehicle's component. The actual numbers that define the range are based upon the relative cosmetic or mechanical significance of the component. For example, your vehicle's chrome quality counts more than the quality of the windshield wiper blade; therefore the maximum points awarded for chrome is higher. The grade is the appraiser's subjective evaluation of the component on your vehicle. A maximum award means that the component is the same quality as found on a new model vehicle.

When no component exists for your vehicle, the appraiser enters "N/A" (not applicable) under grade. When a component is missing because it has been removed, the appraiser enters "M" (missing) under grade.

When totaled, N/A scores are not counted in the category called "Adjusted Total Possible Points". Therefore they do not count against your vehicle. (For example, a two seater would not lose points because it lacked a back seat.) Missing components however do count against your vehicle. When a component is missing, the appraiser subtracts the maximum number in the range from your vehicle's potential total.

If your vehicle has some special historical significance, the appraiser is free to add a dollar value based on the authenticity of the information provided. At your option, the appraiser can also add points depending on the results of a test drive.

To determine your vehicle's value, the appraiser takes the total possible points and corrected vehicle grade and compares them to arrive at a percentage. The percentage is then applied to the value of a "perfect" vehicle. A perfect vehicle is a car similar to yours but in perfect condition with maximum options. Once the appraiser determines the grade of your vehicle and the value of a perfect vehicle, he can calculate the value of your vehicle. This number is found at the end of the report.

Today's Date 1/18/09	Appraisal Date: 12/20/08
Client Name:	
Client Address 1	
Client Address 2	
Client City/St/Zip: Gander	NL
Client Phone:	
Registered Owner Same	
Legal Owner Same	
Legal Owner Address 1:	
Legal Owner Address 2:	
Legal Owner City/St/Zip:	
Referred By	
Make of Vehicle Chevrolet	
Year 1981	
Model Camaro Z28	
License # AAR 121	
Body Type COUPE	
Engine Type 350 4 BL	
Transmission Type 4 SPD STD	
Exterior Color Black	
Interior Color Beige	
Mileage 10657	
Aprx # of Miles Driven/Yr: 100	
Vehicle ID # 1G1AP87L2BN125174	

VEHICLE EVALUATION SECTION

Overall Subjective Appearance:

Very low mileage original vehicle.

GENERAL INFORMATION

RECENT REPAIRS: (No Point Value Awarded)

REPAIRS:

See attached notes.

N Engine

N Transmission/Clutch

N Tires

N Paint and Body

N Upholstery

N Suspension

N Other (Explain)

GRADE SCALE (Page 1 of 3)

LOCATION/COMPONENT	RANGE	GRADE
INTERIOR		
front seat, left	0-5	5.0
front seat, right	0-5	5.0
rear seats	0-5	5.0
door panel, left	0-3	3.0
door panel, right	0-3	3.0
rear side panel, right	0-3	3.0
rear side panel, left	0-3	3.0
dash or dash pad	0-4	4.0
instrument panel	0-4	4.0
trim	0-3	3.0
headliner	0-5	5.0
sunvisors	0-2	2.0
door sill plates	0-4	4.0
steering wheel	0-4	4.0
pedals	0-2	2.0
ear view mirror	0-2	2.0
Column Total (57 possible points)		57

LOCATION/COMPONENT	RANGE	GRADE
INTERIOR (Cont.)		
carpet, front	0-3	3.0
carpet, rear	0-3	3.0
mats	0-2	2.0
rubber around doors	0-3	3.0
TRUNK COMPARIMENT		
mat	0-2	2.0
side panels or inner walls	0-2	2.0
spare wheel and tire	0-2	2.0
spare cover	0-2	2.0
paint, underside of deck lid	0-3	3.0
paint, trunk sills	0-3	3.0
carpet	0-3	3.0
jack/tools	0-3	3.0
ENGINE COMPARIMENT		
no visible oil/water leaks	0-3	3.0
unpainted/plated metal	0-3	3.0
Column Total (37 possible points)		37

GRADE SCALE (Page 2 of 3)

LOCATION/COMPONENT	RANGE	GRADE
ENGINE COMPARIMENT (Cont.)	Y	
exhaust manifolds	0-4	3.0
transmission housing	0-3	3.0
paint, or chrome air cleaner	0-2	2.0
paint, or chrome valve cover	0-2	2.0
paint,fan,pulleys,brackets	0-2	2.0
paint, castings	0-2	2.0
radiator	0-3	3.0
belts	0-3	3.0
hoses and clamps	0-3	3.0
compartment bare metal	0-3	3.0
compartment rubber	0-3	3.0
compartment wiring	0-3	3.0
compartment battery	0-2	2.0
compartment engine decals	0-2	2.0
fuel system, fuel lines	0-3	3.0
fuel system, carb/fuel injection	0-3	3.0
brakes, master cylinder	0-4	4.0
wipers, wiper motor	0-3	3.0
generator/alternator	0-3	3.0
UNDERCARRIAGE	344	
tires and chassis	0-4	4.0
wheels or mags	0-4	4.0
heel covers	0-2	N/A
Column Total (63 possible points)		60

LOCATION/COMPONENT	RANGE	GRADE
UNDERCARRIAGE (Cont.)		
shocks	0-4	4.0
fuel and brake lines	0-2	2.0
springs and stabilizer bar	0-2	2.0
steering linkage	0-3	3.0
exhaust system	0-3	3.0
fuel tank	0-3	3.0
body braces	0-4	4.0
general underbody	0-4	3.0
EXTERIOR (appearance, not ope	eration)	- W-110-1
headlamps (original, general condition)	0-2	2.0
lenses (marker, turn signal)	0-4	4.0
tail light lenses	0-2	2.0
outside mirror(s)	0-3	3.0
radio antenna(s)	0-2	2.0
wiper arm(s)	0-2	2.0
wiper blade(s)	0-2	2.0
emblems	0-3	3.0
weather molding, trunk	0-3	3.0
rubber, or "fuzzes", in window track	0-3	3.0
glass, nicks or scratches	0-3	3.0
body paint and finish/gloss	0-5	5.0
body paint, no chips or scratches	0-5	5.0
chrome quality	0-5	5.0
Column Total (69 possible poi	nts)	68

GRADE SCALE (Page 3 of 3)

LOCATION/COMPONENT	RANGE	GRADE
EXTERIOR (Cont.)		520000000000000000000000000000000000000
fit and alignment of doors	0-3	3.0
fit and alignment of hood	0-3	3.0
fit and alignment of trunk	0-3	3.0
fit and alignment of other panels	0-3	3.0
fit and alignment of bumpers	0-3	3.0
trim	0-4	4.0
OPERATIONAL CHECK		
starter	0-2	2.0
idle	0-3	3.0
engine (sounds)	0-4	4.0
exhaust (appearance)	0-4	4.0
lights	0-4	4.0
signals	0-4	4.0
horn(s)	0-3	3.0
windows	0-3	3.0
wiper(s)	0-3	3.0
Column Total (49 possible poi	.nts)	49

LOCATION/COMPONENT	RANGE	GRADE
OPERATIONAL CHECK (Cont.)	
lighter	0-2	2.0
clock	0-3	3.0
seat adjustment	0-3	3.0
interior lights	0-2	2.0
gauges/lights	0-3	3.0
other	0-3	N/A
MISCELLANEOUS ITEMS		
radio	0-3	3.0
air conditioning	0-3	N/A
heater	0-3	3.0
Column Total (25 possibl	e points)	19

Test Drive (Optional): N/A Total Points (Maximum of 20 Points Possible)

The appraiser may award a maximum of 20 points depending on the results of the test drive.

NOTE: If the appraiser does not perform a test drive, the 20 points will not be counted against the car. The 20 points will be included in the total N/As and then all the N/As will be deducted from the 320 given as the Grading Standard, Total Possible Points.

a test drive is performed, the appraiser will check for the operation of the clutch, transmission, engine, speed control, brakes, cornering/handling, ride, and body integrity.

NOTES

ENGINE COMPARTMENT	Numbers matching 350 four barrel and four speed manual transmission. The engine and compartment are in factory condition with the exception of some minor browning of the exhaust manifolds. The owner removed the original panel above the radiator when the vehicle was new and carefully stored it to preserve the factory decals. A factory replacement has been installed. The original battery has been stored.	
TRUNK	The interior of the trunk compartment has its factory finish in excellent condition. The original spare, jack and tools are in excellent unused condition.	
UNDERNEATH	In factory condition with the exception of dealer applied undercoating when the vehicle was delivered. All suspension components have factory finishes and inspection marks. The exhaust is in new condition.	
INTERIOR	The interior is in pristine original condition. An aftermarket stereo was installed in the console as well as speakers in the door panels when the vehicle was new. The original console and door panels were removed and carefully stored. Factory replacements were used for the stereo installation.	
BODY	Straight original low mileage body that has been in heated storage and has never had any rust or collision damage.	
PAINT	Vehicle has its factory applied paint and has no chips or scratches. The stripes are in excellent condition.	
WHEELS	Original 15 inch Z28 aluminum wheels with the factory finish. The wheels and centers are in excellent condition.	
TIRES	Four B.F. Goodrich P225/70R15 in new condition. The owner removed the four original Uniroyal P225/70R15 when the vehicle was delivered new. They are vacuum sealed and stored.	

GLASS	All glass is original and has no chips or scratches.
TRIM	All trim pieces, emblems and light lenses are original and in excellent condition.

1. Current Market Listed Value:	\$ 25,253.00
2. Grading Standard, Total Points Possible:	320
3. Adjusted Points: (Sum of all N/As)	28
4. Adjusted Total Possible points:	292
5. Vehicle's Score:	290
6. The Appraiser rates this Vehicle as a:	99 Point Car
7. Vehicle Appraised Value Based on Points:	\$ 25,000.47
8. Special Historical Adjustment:	\$ 0.00
9. Actual Appraised Value of car:	\$ 25,000.47
Appraiser 2 2 Chaffy D	[2]

Comments:


Very nicely preserved vehicle. The only demerits from factory new condition are some browning of the exhaust manifolds and dealer applied undercoating.

Special Historical Information (Enter N/A if none exists): $\ensuremath{\text{N/A}}$

















































LAKEVIEW CHRYSLER



Jeep

150 Armstrong Blvd. P.O. Box 321 Gander, NL A1V 1W7

Jeep



Telephone: (709) 651-4000 Fax: (709) 256-3061

Email: lakeview@nfld.com www.lakeviewchrysler.com



NOVEMBER 21, 2008

I HAVE APPRAISED A 1981 CHEV CAMARO Z28 FOR
THE FAIR MARKET VALUE OF THIS
CAR IS \$ 35,000. IN MY PROFESSIONAL OPINION, THIS
CAR IS IN PRISTINE CONDITION AND HAS EXTREMELY
LOW MILEAGE OF 10560 KM. THE SERIAL NUMBER IS
1G1AP87L2BN125174.

THANK YOU.

MEVIN DICKEY MANAGER LAKEVIEW PLYMOUTH CHRYSLER 150 ARMSTRONG BLVD GANDER NL, A1V 1W7



we have rout in mind

《 1986年 1987年 1987年 1987年 1